Execution PLC-01

1. Controller card standard version

Typedesignation: BM4-O-PLC-01-00-02

Part No.:365845

Function: controller card standard version Presuppositions: BM44XX-XX-XXXXXX-XX

Information of nameplate: BM4-O-PLC-01 -00 02 777 ууу LP 3.0021.01.Xxx D900: 6.1276.xxxx D500 1: 6.1284.xxxx D500 2: 6. 1314.xxxx with Single **Axis Motion Control Support** FPGA-SW Bootloader Firmware LP-Version 6.1276 6.1284 6.1314 000 000 3.0021.01 D00 0102 0101 0101 D00 000 001 0103 0102 0102 D01 002 001 0103 0103 0104 D01 001 003 0103 0104 0105 D01 001 004 0104 0106 0103 D01 001 005 0103 0104 0107 D01 001 006 0104 0107 0106 D02 002 006 0106 0104 0107 D02 002 007 0106 0104 0109 D02 002 800 0106 0104 0110 D₀2 002 009 0106 0105 0111 D03 003 800 0106 0105 0111 D02 002 010 0106 0105 0112 D03 003 010 0106 0105 0112

Hardware history

The printed circuit board 3.0021.01.D00 is the first official version.

The printed circuit board 3.0021.01.D01 is introduced with AT222_03 from October 31, 2003.

- Adaptation of the printed circuit board to the equipment with optional NOVRAM (LP 3.0032.03) The printed circuit board 3.0021.01.D02 is introduced with AT076 05 from March 21, 2005.
 - Optimized boot behavior (Reset level at the option modules)

The printed circuit board 3.0021.01.D03 is introduced with AT086 07 from March 21, 2007.

Optimized clock signal

The changes are for the software uncritically. New software also runs on old hardware version. Reconstruction of a PLC without Novram in a PLC with Novram is only possible by stick, if the printed circuit board 3.0021.01.D01 is applied.

FPGA software history

The FPGA-software 1.02 is the first official version.

The FPGA-software 1.03 is introduced with AT360 03 from July 23, 2003.

• Implementing of the access for optional NOVRAM

The FPGA-software 1.06 is introduced with AT076_05 from March 23, 2004.

- Synchronization behavior improves with restart of the synchronization
- Improvement of the BACI-Timing

Boot loader software history

The Boot loader software 1.01 is the first official version.

The Boot loader software 1.02 is introduced with AT360 03 from July 23, 2003.

Implementing of the access for optional NOVRAM

The Boot loader software 1.03 is introduced with AT222_03 from the October 31, 2003.

Adaptation to the boot-behavior of the optional NOVRAM

The Boot loader software 1.04 is introduced with AT016_03 from June 30, 2004.

 Possibility of the storage of the serial number into the PLC and adjustment to the of the controller, it is waited now for the automatic controller signals

The Boot loader software 1.05 is introduced with AT200_05 from July 30, 2005.

Adaptation to new memory layout

Firmware history

The Firmware 1.01 is the first official version.

The Firmware-software 1.02 is introduced with AT360_03 from July 23, 2003.

• Extension of the data management in the controller from 4 to 8 data records which the PLC can also manage now

The Firmware 1.03 is not official introduced.

The Firmware software 1.04 is introduced with AT222 03 from October 31, 2003.

Adaptation to the boot-behavior of the optional NOVRAM

The Firmware software 1.05 is introduced with AT016 04 from May 17, 2004.

- Adaptation for the new versions of the components MOTION_TYPES_20bd04, MOTION CONTROL 20bd04
- Change of the command MC_Power, now the impulse is also released by not receipted warnings
- Modification of master CANopen Master network management at the initialization of the slaves
- Modification of Single Axis uses CANopen now in synchronous mode of operation with turned on Ethernet from master CANopen SW version 01.10
- Correction of the FBs MC_HomeInit_LimitSwitch and MC_HomeInit_HomeSwitch, now it describes the correct parameters for delay.
- Correction of the mistake evaluation with the service data communication with CANsync axes.
- Correction of the function MC_Stop
- Correction of the standardisation of the aim speed with MC_MoveVelocity for CANsync axes
- Correction of the adaptation of the object allocation for Homingoffset after change of the CANopen Slaves

The Firmware software 1.06 is introduced with AT347 04 from August 23, 2004.

- Adaptation of Motion Control in controller software 03
- Correction of the behavior while releasing of a quick stop.
 This was recognized by Motion Control and was announced by the MC_Power. However, this condition could not be given a receipt by Motion Control any more or be left.

The Firmware software 1.07 is introduced with AT384 04 from September 22, 2004.

• The initialization of the drives was partly broken off by Motion Control by an incorrect function to the choice and evaluating of the controller firmware version. These axes could not be steered in the mistake case by Motion Control.

The Firmware software 1.09 is introduced with AT073_05 from April 08, 2005.

• Integration of b maXX 2300 / b maXX 2400

The Firmware software 1.10.

• It was manufactured only by the development and exist only for the completeness concerning the name plates

The Firmware software 1.11 is introduced with AT200_05 from June 30, 2005.

Motion Control function extension Multi Axis Motion control for b maXX 2300

The Firmware software 1.12 is introduced with AT200_07 from February 27, 2007.

- Support of configuration Motion Control with ProMaster
- Support of configuration BACI communication for Motion Control with ProMaster
- Support of configuration of CANopen communication for Motion Control with ProMaster
- Support of configuration of EtherCAT communication for Motion Control with ProMaster
- Integration of function for 64 Bit multiplication with division
- Integration of function for FB MC_ReadAxisStatus
- Integration of GearInAngle for b maXX 4400.

Indication

From Firmware 1.01 the basic devices with SW01 can be served with Motion Control.

From Firmware 1.06 the basic devices with SW03 can be served with Motion Control.

The firmware-version has to adapt absolutely on the newest state by the exchange of the basic devices of SW01 on SW03

Update-Indication

Firmware and FPGA-SW always together update at last version.

2. Controller card with memory expansion


Typedesignation: BM4-O-PLC-01-01-02

Part No.: 378100

Function: Controller card with 56KB Novram and 4MB Flash

Presuppositions: BM44XX-XX-XXXXXX-XX

Information of nameplate:



Hardware history

The printed circuit board 3.0021.01.D01 is the first official version.

The printed circuit board 3.0021.03.D01 is the first official version.

The printed circuit board 3.0021.01.D02 is introduced with AT076_05 from March 21, 2005.

Optimized boot behavior (Reset level at the option modules)

The printed circuit board 3.0021.01.D03 is introduced with AT086 07 from March 21, 2007.

Optimized clock signal

FPGA software history

The FPGA-software 1.03 is the first official version.

The FPGA-software 1.06 is introduced with AT347_04 from August 18, 2004.

- Changes are necessary, so that Motion Control can be used with b maXX controller LC2.
- Acknowledgement of the condition is possible, if guick stop was released

Boot loader software history

The Boot loader-software 1.03 is the first official version.

The Boot loader-software 1.04 is introduced with AT016_04 from May 17, 2004.

• Possibility of the storage of the serial number into the PLC and adaptation to the of the controller, it is waited now for the automatic controller signals

The Boot loader-software 1.05 is introduced with AT200 05 from June 30, 2005.

Adaptation to new memory layout

Firmware history

The Firmware 1.04 is the first official version.

The Firmware 1.05 is introduced with AT016_04 from June 30, 2004.

- Adaptation for the new versions of the components MOTION_TYPES_20bd04, MOTION_CONTROL_20bd04
- Change of the command MC Power, now the impulse is also released by not receipted warnings
- · Modification of master CANopen Master network management at the initialization of the slaves
- Modification of Single Axis uses CANopen now in synchronous mode of operation with turned on Ethernet from master CANopen SW version 01.10
- Correction of the FBs MC_HomeInit_LimitSwitch and MC_HomeInit_HomeSwitch, now it describes the correct parameters for delay.
- Correction of the mistake evaluation with the service data communication with CANsync axes.
- Correction of the function MC Stop
- Correction of the standardisation of the aim speed with MC_MoveVelocity for CANsync axes
- Correction of the adaptation of the object allocation for Homingoffset after change of the CANopen Slaves

The Firmware software 1.06 is introduced with AT347_04 from August 23, 2004.

- Adaptation of Motion Control in controller software 03
- Correction of the behavior while releasing of a quick stop.
 This was recognized by Motion Control and was announced by the MC_Power. However, this condition could not be given a receipt by Motion Control any more or be left.

The Firmware software 1.07 is introduced with AT384_04 from September 22, 2004.

• The initialization of the drives was partly broken off by Motion Control by an incorrect function to the choice and evaluating of the controller firmware version. These axes could not be steered in the mistake case by Motion Control.

The Firmware software 1.09 is introduced with AT073 05 from April 08, 2005.

Integration of b maXX 2300 / b maXX 2400

The Firmware software 1.10.

• It was manufactured only by the development and exist only for the completeness concerning the name plates

The Firmware software 1.11 is introduced with AT200 05 from June 30, 2005.

Motion Control function expansion Multi Axis Motion control for b maXX 2300

The Firmware software 1.12 is introduced with AT200_07 from February 27, 2007.

- Support of configuration Motion Control with ProMaster
- Support of configuration BACI communication for Motion Control with ProMaster
- Support of configuration of CANopen communication for Motion Control with ProMaster
- Support of configuration of EtherCAT communication for Motion Control with ProMaster
- Integration of function for 64 Bit multiplication with division
- Integration of function for FB MC_ReadAxisStatus
- Integration of GearInAngle for b maXX 4400.

Indication

From Firmware 1.01 the basic devices with SW01 can be served with Motion Control.

From Firmware 1.06 the basic devices with SW03 can be served with Motion Control.

=> By the exchange of the basic devices of SW01 on SW03 the firmware-version has to adapt on the newest state.

Update-Indication

Firmware and FPGA-SW always together update at last version.


2. inactive Controller cards

Typedesignation: BM4-O-PLC-01-00-00

Part No.: 350438 Function: Controller card

Presuppositions: BM44XX-XX-XXXXXXXXX

Information of nameplate:



Hardware history

The printed circuit board 3.0021.01.B02 is the first official version.

The printed circuit board 3.0021.01.D00 is introduced with AT161 03 from November 20, 2003.

· Admission of a new layout

The printed circuit board 3.0021.01.D01 is introduced with AT222_03 from October 31, 2003.

New insertion

Boot loader software history

The Boot loader-software 1.01 is the first official version.

Firmware history

The Firmware 1.01 is the first official version.

FPGA software history

The FPGA-software 1.02 is the first official version.

Indication:


It is replaced by PLC01-00-02.

Typedesignation: BM4-O-PLC-01-00-01

Part No.: 363623 Function: Controller card

Presuppositions: BM44XX-XX-XXXXXXXX

Information of nameplate:



Hardware history

The printed circuit board 3.0021.01.B02 is the first official version.

The printed circuit board 3.0021.01.D00 is introduced with AT542_02 from November 20, 2003.

• Admission of a new layout

The printed circuit board 3.0021.01.D01 is introduced with AT222 03 from October 31, 2003.

New insertion

Boot loader software history

The Boot loader-software 1.01 is the first official version.

Firmware history

The Firmware 1.01 is the first official version.

FPGA software history

The FPGA-software 1.02 is the first official version.

Indication:

It is replaced by PLC01-00-02.