



IECEX Facility Assessment Report Summary

INTERNATIONAL ELECTROTECHNICAL COMMISSION IEC Certification System for Explosive Atmospheres

for rules and details of the IECEx Scheme visit www.iecex.com

FAR Ref. No.: **NL/DEK/FAR11.0019/12**

Page 1 of 1

Issuing ExCB: **DEK - DEKRA Certification B.V.**

Date of issue: **:2024-01-18**

Status :**Issued**

Audit date:
2023-09-20

Valid Until:
2026-09-20

Location(s) audited:

Baumüller Benelux B.V.
Regenbeemd 6
4825 AT Breda
The Netherlands
Netherlands

Service Facility:

Baumüller Benelux B.V.
Regenbeemd 6
4825 AT Breda
The Netherlands
Netherlands

Details of change: **Reassessment**

Type of work Covered **Repair and overhaul of Ex d, Ex e, Ex n, Ex t motors.**
by Service Facility: **Repair, overhaul and maintenance of non-electrical equipment Ex d and Ex h, mainly gearboxes and pumps, non-electrical type of protection constructional safety "c", control of ignition sources "b", liquid immersion "k".**

Related FARs:

[NL/DEK/FAR11.0019/00](#)
[NL/DEK/FAR11.0019/03](#)
[NL/DEK/FAR11.0019/06](#)
[NL/DEK/FAR11.0019/09](#)

[NL/DEK/FAR11.0019/01](#)
[NL/DEK/FAR11.0019/04](#)
[NL/DEK/FAR11.0019/07](#)
[NL/DEK/FAR11.0019/10](#)

[NL/DEK/FAR11.0019/02](#)
[NL/DEK/FAR11.0019/05](#)
[NL/DEK/FAR11.0019/08](#)
[NL/DEK/FAR11.0019/11](#)

Related IECEx Service
Facility Certificates:

Comments: